




ELEMENT - The Quarter 380 Luxury Apartments



Schedule of Accommodation

Lower Ground Floor

- Commercial units
- Gymnasium
- Cinema /Study
- Games /Lounge
- Comms Room
- Refuse store
- Cycle store
- Plant
- Management Office
- Lift access
- Undercroft Car parking


Upper Ground Floor

- 2 no. 1 Bedroom Apartments
- 1 no. 2 Bedroom Apartments
- 68 no. Studios
- 19 no. Cluster Rooms
- 4 no. Cluster Lounges

<u>Level 1 - 5</u>

- 29 no. 1 Bedroom Apartments
- 12 no. 2 Bedroom Apartments
- 255 no. Studios
- 42 no. Cluster Rooms
- 13 no. Cluster Lounges
- Roof terrace

New Build Two Phase Development to Create Residential Apartments Commercial Units & Ancillary Accommodation



The seven storey new build development generally comprises:

- Excavation and formation of new foundations
- Below and above ground drainage
- New ground supported and part suspended concrete floor slab
- Seven storey steel frame structure
- External clad and glazed envelope
- Suspended metal deck and concrete floors
- Flat roof structures and finishes
- Aluminium curtain walling, external windows and doors and shopfronts
- External balconies and balustrades
- Internal sub-division of retail units, ancillary accommodation and apartments with non-loadbearing block and stud partitions
- Installation of plumbing services and mechanical services
- Installation of electrical services
- Installation of new lift car access
- Installation of kitchen and sanitary fittings
- New internal finishes, joinery fittings and decorations
- Repairs and making good steel framework and floor structures

Land at Corner of Low Hill and West Derby Road, Liverpool L6

Site Location





Aerial view of Element – The Quarter site location

Aerial view of Element – The Quarter site location

Building Structure

ELEMENT – The Quarter, Liverpool New Build Development

Sub-Structure & Super-Structure Construction Progress

A U G U S T 2 0 2 1

Site compound and temporary supplies	50% complete
Demolition and site clearance	100% complete
Ground infill and site levelling	100% complete
Piling foundations	100% complete
Retaining walls, concrete beam foundations	100% complete
Underground drainage	90% complete
Ground floor slab construction	0% complete
Steel frame structure	92% complete
Upper suspended steel floor structure	70% complete
Internal staircase structure	100% complete
Sub-structure masonry walls	100% complete
Fire coating steel framework	60% complete
Structural framework forming external walls	5% complete
Scaffolding & mast climber access	40% complete
Flat roof structure	10% complete
Flat roof coverings including balconies	0% complete
Weatherboarding	0% complete
External windows /doors & curtain walling	0% complete
External wall insulation & cladding	0% complete
Mansafe system	0% complete

AUGUST 2021



Brunswick Road - Site view

Brunswick Road - Site view

AUGUST 2021



Brunswick Road - Site view

West Derby Road - Site view

AUGUST 2021



Walker Street - Site view

Walker Street - Site view

AUGUST 2021



Walker Street - Site accommodation

Walker Street - Site entrance


AUGUST 2021



Electrical supply installed

Material Storage – Intumescent paint

AUGUST 2021



Under croft parking area

Inner courtyard area

AUGUST 2021



Inner courtyard view, steel framework structure & mast climbers

Material storage and site access plant

AUGUST 2021



Inner courtyard view steel framework structure & scaffolding

Inner courtyard view steel framework structure & scaffolding

AUGUST 2021



Steel framework structure to upper floors – Streel frame modifications and balcony removal to be complete

Steel framework structure to upper floors

AUGUST 2021



Steel framework structure to upper floors

Steel framework structure to upper floors

AUGUST 2021



Steel framework structure lower floors – Fire protective coatings ongoing

Steel framework structure lower floors – Fire protective coating ongoing

AUGUST 2021



Steel framework structure lower floors – Fire protective coatings ongoing

Temporary health and safety signage

AUGUST 2021



Steel framework structure to upper floors – Concrete pouring due to re-commence

Steel framework structure to upper floors – Fire protective coatings commenced

AUGUST 2021



Bathroom pods delivered for installation – Pod testing and itinerary checks currently ongoing



Bathroom pods delivered for installation - Pod testing and itinerary checks currently ongoing

AUGUST 2021



Bathroom pods delivered for installation – Pod testing and itinerary checks currently ongoing



Bathroom pods delivered for installation – Pod testing and itinerary checks currently ongoing

AUGUST 2021



Site access road & material storage

Site access road & material storage


AUGUST 2021



Site access barriers installed

Second floor emergency escape plan

AUGUST 2021





Core hole complete, drilling works ongoing

Core drilling ongoing


AUGUST 2021



Core drilling ongoing

Material storage


AUGUST 2021



Temporary lighting installation ongoing as required

Upper floor fire point

AUGUST 2021



Steel frame stair core structure and lift overrun



Steel frame structure and metal decking ongoing

AUGUST 2021



Metal decking structure to upper floors

Metal decking structure to upper floors


AUGUST 2021



Metal decking structure to upper floors ongoing

Metal decking structure to upper floors ongoing

AUGUST 2021



Metal deck roof structure

Metal deck roof structure

AUGUST 2021



Metal deck roof structure re-commenced to upper floors

Metal deck roof structure

AUGUST 2021




Metal decking structure to lower floors – Concrete pouring yet to re-commence

Metal decking structure to lower floors – Concrete pouring yet to re-commence

AUGUST 2021



Fire call point adjacent to stair core



Stair core and temporary handrails installed

AUGUST 2021



Site access barriers and turnstile installed

Site access barriers and turnstile installed


AUGUST 2021



Courtyard scaffold – Scaffold safety checks currently ongoing

Walker Street scaffold – Scaffold safety checks currently ongoing

AUGUST 2021



Aerial view of the courtyard, site storage and access road

Aerial view of the courtyard, site storage and access road

AUGUST 2021



Inner courtyard view steel framework structure

Inner courtyard view steel framework structure

AUGUST 2021



Steel framework structure and decking works ongoing

Steel framework structure and decking works ongoing

AUGUST 2021



Steel framework and foundation modifications

Steel framework and foundation modifications

AUGUST 2021



Steel framework and foundation modifications

New retaining wall structure commenced

AUGUST 2021



Site access plant

Site access plant

AUGUST 2021



Site materials stored

Waste skips

TO FIND OUT MORE ABOUT

ELEMENT – The Quarter, Liverpool

PLEASE CONTACT



W W W . L E G A C I E . C O . U K

By Appointment Only Unit 4 Connect Business Village Liverpool, L5 9PR +44 (0) 151 207 9990