legacie



Parliament Square – Phase 1 Block D 97 Luxury Apartments



Land at corner of Upper Parliament Street & Great St George Street, Liverpool L1

Schedule of Accommodation Block 'D'

Basement

- Carparking
- Sub-Station
- Plant

Ground Floor

- Retail units
- Refuse store
- Hard and soft landscaping

Floors 1 - 11

- 31 no. Studio Apartments
- 22no. 1 Bedroom Apartments
- 44 no. 2 Bedroom Apartments

New Build Two Phase Development to Create Residential Apartments Retail Units & Basement Parking




 $Land\ at\ corner\ of\ Upper\ Parliament\ Street\ \&\ Great\ St\ Ge\ orge\ Street,\ Li\ verpool\ L1$

The eleven storey new build development generally comprises:

- Demolition of adjoining structures and perimeter walls
- Site clearance and levelling
- Site investigations and trial holes
- Excavation and formation of new foundations
- Below and above ground drainage
- New ground supported and part suspended concrete floor slab
- Eighteen storey steel frame structure
- External clad and glazed envelope
- Suspended metal deck and concrete floors
- Flat roof structures and finishes
- Aluminium curtain walling, external windows and doors and shopfronts
- External balconies and balustrades
- Internal sub-division of retail units and a partments with non-load bearing block and stud partitions
- Installation of plumbing services and mechanical services
- Installation of electrical services
- Installation of new lift car access
- Installation of kitchen and sanitary fittings
- New internal finishes, joinery fittings and decorations

Site Location



Liverpool Cathedral

Ariel View of the site prior to demolition


Aerial view of the site location of Parliament Square

Building Structure

Parliament Square, Liverpool New Build Development

Basement slab construction	100% complete
Ground floor slab construction	100% complete
Concrete deck floor construction to upper floors	100% complete
Lift and staircase core concrete structure	100% complete
Concrete frame structure	100% complete
Internal staircase structure	100% complete
Structural framework forming external walls	99% complete
Scaffolding & mast climber access	100% complete
Flatroof covering including balconies	79% complete
Weatherboarding	99% complete
External windows / doors	99% complete
Curtain walling	0% complete
Brickwork & insulation	76% complete
External wall cladding and insulation	42% complete





Block D Section B – Viewed from Parliament Street

Block D Section A – Viewed from Greenland Street






Block D Section B and C – Viewed from Parliament Street

Block D Section A, B and C – Viewed from Greenland Street





Block D Section B – Viewed from Crump Street

Block D Section A & C – Viewed from Crump Street





Balcony cladding installation progressed

Balcony cladding installation progressed





Balcony cladding installation progressed


Balcony cladding installation progressed



Balcony cladding installation progressed

Block D Section A – Viewed from roof terrace






Block D – viewed from Block B podium

Block D – viewed from Block B podium





Block D Section A – Roof installation progressing

Block D Section A – Roof installation complete






Block D Section B – Roof installation progressing

Block D Section B – Photovoltaics on site





Block D Section A – Soil vent pipe installation

Block D Section C – Podium construction ongoing

Internal Fit-out Block 'D'

Parliament Square, Liverpool New Build Development

Liftinstallation	0% complete
Partition walls installation	95.5% complete
Apartment ceiling installation	93% complete
Plaster finishes walls and ceilings	88.5% complete
1st fix electrical	85% complete
1st fix plumbing and heating	94% complete
Kitchen units and appliances	53% complete
Second fix electrical	52% complete
Second fix plumbing and heating	62% complete
Doorframes	63% complete
Bathroom sanitary fittings	85% complete
Wall and floor tiling	90% complete
Carpet and floor finishes	34% complete
Doors and ironmongery	63% complete
Decorations	28% complete

October 2023





October 2023





September 2023





October 2023





October 2023





October 2023





October 2023









Mist coat application ongoing

Mist coat application ongoing






Wall covering installation ongoing

Wall covering installation ongoing





Electrical heater installation ongoing

Final fix installation ongoing





Laminate flooring installation ongoing

Laminate flooring installation ongoing





Installation of kitchen units ongoing

Installation of kitchen worktop ongoing

October 2023





Sink installation ongoing Tap installation ongoing





Appliance installation ongoing

Appliance installation ongoing





Appliance installation ongoing

Appliance installation ongoing





Sanitary installation ongoing

Sanitary installation ongoing





Sanitary installation ongoing

Skirting board installation ongoing




M&E installation progressing



Distribution installation ongoing






Ventilation installation ongoing

Ventilation installation ongoing

October 2023





Kitchen installation ongoing Kitchen installation ongoing

October 2023





Plaster skim coat ongoing Plaster skim coat ongoing

October 2023





Plaster skim coat ongoing Plaster skim coat ongoing





Apartments second side boarded


Apartments second side boarded






Fire rated putty to socket backbox

Socket face plateinstalled






Pattress installation to staircore

Hoist apartment close-ups ongoing






Pattress installation to staircore

Insulation installed to soil vent pipework





Water tank installation ongoing

Commercial sprinkler system installation ongoing


October 2023





Lifts onsite Cladding panels onsite





Electrical cables onsite for mains connection

Base for sprinkler tank poured






Cladding panels onsite

Water tank installation ongoing

October 2023





Mirrors onsite Cladding panels onsite

October 2023





Decoration equipment Plastering equipment

Parliament Square, Liverpool

PLEASE CONTACT

legacie

W W W . L E G A C I E . C O . U K

By Appointment Only
Unit 4 Connect Business Village
Liverpool, L5 9PR
+44 (0) 151 207 9990