## legacie



## The Summit 145 Luxury Apartments











#### **Schedule of Accommodation**

#### **Basement**

- Car parking 45 no. spaces
- Lift access
- Plant

#### **Ground Floor**

- Commercial units
- Gymnasium
- 2 no. 1 Bedroom Apartments
- Comms Room
- Refuse store
- Cycle store
- Plant
- Sub-station
- Hard and soft landscaping

#### Floors 1 - 10

- 70 no. 1 Bedroom Apartments
- 73 no. 2 Bedroom Apartments
- Roof terraces

#### New Build Development to Create Residential Apartments Commercial Units & Basement Parking





Land at corner of Parliament Street & Caryl Street, Liverpool L8 5RW

### The eight & eleven storey new build development generally comprises:

- Excavation and formation of new foundations
- Below and above ground drainage
- New ground supported and part suspended concrete floor slab
- New concrete ramp access to basement parking
- Ten and Eleven storey steel frame structure
- External clad and glazed envelope
- Suspended metal deck and concrete floors
- Flat roof structures and finishes
- Aluminium curtain walling, external windows and doors and shopfronts
- External balconies and balustrades
- Internal sub-division of commercial units, gym and apartments with non-loadbearing block and stud partitions
- Installation of plumbing services and mechanical services
- Installation of electrical services
- · Installation of new lift car access
- Installation of kitchen and sanitary fittings
- · New internal finishes, joinery fittings and decorations
- · Repairs and making good building fabric and internal finishes to the partially completed building

#### Site Location





Aerial view of The Summit site location


Aerial view of The Summit site location

## **Building Structure**

The Summit, Liverpool New Build Development

# Sub-Structure & Super-Structure Construction Progress

|  | Original Scheme | On-site Progression |
|--|-----------------|---------------------|
| Underground drainage                                       | 100% complete   | 100% complete       |
| Floor slab construction                                    | 100% complete   | 100% complete       |
| Steel frame structure                                      | 100% complete   | 100% complete       |
| Upper suspended steel floor structure                      | 100% complete   | 100% complete       |
| Internal staircase structure                               | 100% complete   | 100% complete       |
| Sub-structure masonry walls                                | 100% complete   | 100% complete       |
| Fire coating steel framework                               | 95% complete    | 95% complete        |
| Structural framework forming external walls                | 100% complete   | 100% complete       |
| Scaffolding & mast climber access                          | 100% complete   | 100% complete       |
| Flat roof structure  | 100% complete   | 100% complete       |
| Flat roof coverings including balconies                    | 95% complete    | 95% complete        |
| Weatherboarding  | 100% complete   | 100% complete       |
| External windows /doors & curtain walling                  | 90% complete    | 90% complete        |
| External wall insulation & cladding                        | 80% complete    | 85% complete        |
| External wall insulation & cladding investigation & repair | 0% complete     | 85% complete        |
| Mansafe system   | 98% complete    | 98% complete        |
| Brick Work & insulation to elevations                      | 80% complete    | 15% complete        |





Parliament Street site view

Parliament Street site view






Parliament Street site view

Parliament Street site view






Parliament Street site view

Parliament Street site view





Parliament Street site view

Parliament Street site view





External cladding remedial works

Caryl Street site view





External cladding remedial works

External cladding remedial works





External cladding remedial works

External cladding installation





Soffit cladding rail installed

Soffit rain screen cladding installed





External cladding remedial works

External cladding remedial works



Window & glazing installation ongoing

Brindley Street elevation insulation & brickwork ongoing


FEBRUARY 2022






Curtain wall installation Brickwork installation





Man safe system in place

Man safe system in place





Brickwork installation to basement ramp


Brickwork installation to basement ramp






Blockwork installation commenced

Ground Floor site activity





Ground Floor site activity

Ground Floor site activity

## Internal Fit-out

The Summit, Liverpool New Build Development

### Internal Fit-out Construction Progress

|                                     | Original Scheme | On-site Progression |
|-------------------------------------|-----------------|---------------------|
| Core drilling for services          | 100% complete   | 100% complete       |
| Riser installation                  | 100% complete   | 100% complete       |
| Lift installation                   | 98% complete    | 98% complete        |
| Above ground drainage               | 95% complete    | 95% complete        |
| Partition walls installation        | 100% complete   | 100% complete       |
| Apartment ceiling installation      | 100% complete   | 100% complete       |
| Plaster finishes walls and ceilings | 100% complete   | 100% complete       |
| First fix electrical                | 100% complete   | 100% complete       |
| First fix plumbing and heating      | 90% complete    | 67% complete        |
| Kitchen units and appliances        | 60% complete    | 21% complete        |
| Doorframes                          | 70% complete    | 64% complete        |
| Skirting and architrave             | 60% complete    | 64% complete        |
| Bathroom sanitary fittings          | 60% complete    | 74% complete        |
| Wall and floor tiling               | 60% complete    | 71% complete        |
| Carpet and floor finishes           | 50% complete    | 76% complete        |
| Doors and ironmongery               | 50% complete    | 50% complete        |
| Decorations                         | 50% complete    | 60% complete        |
| Second fix electrical               | 60% complete    | 43% complete        |
| Second fix plumbing and heating     | 60% complete    | 43% complete        |
| General fixtures and fittings       | 0% complete     | 0% complete         |




Partition & pattress installed to stairwell

Partition & pattress installed to stairwell



Sprinkler system installation

Stairwell wall boarding installed







Ceiling grid installed

Walls plastered to stairwell







2<sup>nd</sup> coat decoration





Walls boarded to circulation areas

Walls skimmed to circulation areas





Block A – Kitchens installed

Block A - apartment doors & ironmongery installed





Block A – Kitchens installed


Block A – Kitchens installed





Apartment decoration ongoing

Block A – Appliances installed





Block A – Feature walls


Block A – Feature walls





Block A – Feature walls

Block A – Feature walls





Block A – Feature walls

Block A – Feature walls





Block A – Apartment finishes

Apartment decoration ongoing

FEBRUARY 2022





Appliance installation Kitchen unit installation






Block A – Kitchens installed

Doors loaded for installation

FEBRUARY 2022





Carpets installed Window boards installed





Water cylinder and ventilation unit installed

Carpets installed



Bathroom mirrors installed


Bathroom sanitary appliances installed



Bathroom sanitary appliances installed

Bathroom sanitary appliances installed





Bathroom sanitary appliances installed

Bathroom sanitary appliances installed



Installation of bathroom appliances ongoing

Walls & ceilings plastered to stairwell





Water cylinder and ventilation unit installed

Installation of water cylinder ongoing





2<sup>nd</sup> coat decoration

Worktops loaded for installation






2<sup>nd</sup> coat decoration

Apartment doors & ironmongery installed





Apartment doors & ironmongery installed

Apartment doors installed





2<sup>nd</sup> coat decoration

Appliances loaded for installation






Doors installed for terrace link roof access

Doors installed for terrace link roof access





Sprinkler system installation

Electrics consumer unit





Apartment intercom system

Electrics isolation unit






Radiator loaded for installation

Doors loaded for installation



Plaster loaded for application



Carpets loaded for installation





Paint loaded for application

Carpets loaded for installation

#### The Summit, Liverpool

PLEASE CONTACT



W W W . L E G A C I E . C O . U K

By Appointment Only
Unit 4 Connect Business Village
Liverpool, L5 9PR
+44 (0) 151 207 9990